WarpAstron

WARPDRIVE WD-20P

Package Contents

（For latest version, please visit https://www.warpastron.com）

⚠ Check that all of the following items are in your package, If any item is missing, please contact your local dealer or WarpAstron Support Team (support@warpastron.com)

X1

WD-20P Mount Head

X1

Hand Controller
Wired version provided as default

X1

240W 24V AC Adapter
Plug type and availability may vary by
region based on local standards.

X1

DC to DC 5.5*2.5mm Cable

X1

X1

USB-C to USB-A Data Cable
For data connection to PC or astronomy controllers

USB-C to USB-C Gen3.2 Cable
1. For hand controller connecting to mount
2. 100W 5A(Max) PD Power Cable

X1

X1

PD to 12V 5A DC 5.5*2.5mm Cable
1. For saddle CH1 port power output
2. 24V input required for mount power supply

PD to 12V 3A DC 5.5*2.5mm Cable

4mm Hex wrench
For alt range adjustment